



## Contact Us

Office : 256.776.7786  
Email : [sales@firetruckmall.com](mailto:sales@firetruckmall.com)  
Website: [www.firetruckmall.com](http://www.firetruckmall.com)

15410 US Highway 231,  
Union Grove, AL 35175  
Stock #: 08133  
Price: \$20,000

## 1989 Mack Quality Pumper

- 1989 Mack Quality Pumper
- Allison HT740 5-speed Automatic Transmission
- MC688FC Mack Chassis
- Waterous CMYBX 1250 GPM Pump
- Mack E6 270 HP Diesel Engine
- 500 Gallon Tank

○ Intakes: 3 - 6", 1 - 2.5"  
Discharges: 9

○ Pump Hours: 2,404

○ 2 - 1" Booster Reels

○ Mileage: 55,242

○ Ground Ladders: 1 - 35' Extension, 1 - 14'  
Roof & 1 - 10' Attic

○ Additional equipment not included with purchase unless otherwise listed. Mileage readings may not be real-time and should be confirmed.

○ Removed from service 9/2014

Exhaust Fan

100' Extension Cord Reel

Decals have been removed, but  
impression remains

Seats Torn

Holes in Dash from Removed Equipment

Siren: Federal Signal PA300

Apparatus Maintained Every 180 Days

Seller's Information About this Truck:

I did a phone interview with a firefighter who drove this truck. There is no air conditioning, you can just roll down the windows. The truck has pretty good acceleration - and it stops like it should without any problems. It was used in a small beach town (Wrightsville Beach, NC), and so the truck was never driven more than 10 mph over the speed limit. It is reasonably comfortable - and for the ease of driving, it is a relatively smaller truck and the driver said it's pretty easy to get around in this truck on the streets. The maintenance was always done properly and the inspections were always done on time. The truck was painted about five years ago. The garage who handled the maintenance of the truck was really good about the quality of the work they did on the truck.

Decals Have Been Removed, But Impressions Remain. Seats Torn. Holes In Dash From Removed Equipment. Siren: Federal Signal Pa300. Apparatus Maintained Every 180 Days.

The truck has a TS471 Custom Fire Chassis.

There is a gigantic 4-inch thick Mack Truck Service manual (from the Mack world headquarters). This book was made for the town of Wrightsville Beach, NC, on July 21, 1988. The book is NOT a typical 3-ring binder, and has 19 tabbed sections. The book is in very good shape.

The sections of the book are:

General Date - Fastener Torque Manual;  
Engine - 6 Cylinder, Four Valve Head (4VH) Overhaul Manual (This Section Is About 140 Pages); Fuel System; Cooling System; Electrical System; Clutch Removal Manual; HFB70 Service Manual by TRW; Rear Axels/Carriers; Frame, Spring, and Suspension; Wheels, Rims, and Tires; Air Brake System; MH Cab Repair; Engine Bearing Failure Analysis;



Brindlee Mountain Fire Apparatus is one of the world's largest used fire truck sales and service companies. Based just outside of Huntsville, Alabama, the company has forty-five full-time personnel occupying over 12,000 square feet. Our mechanics, all of whom are EVT certified, perform pump tests, general repairs, preventative maintenance, and body, collision, and paint work on over 500 used fire trucks every year. Visit us online at [www.firetruckmall.com](http://www.firetruckmall.com)